
## General Notes:

- A. INSTALLATION OF CEILING HUNG TOILET PARTITIONS MUST BE IN ACCORDANCE WITH MANUFACTURERS INSTRUCTIONS.
- B. IT IS THE DISTRIBUTOR'S
  RESPONSIBILITY TO CONSULT A
  STRUCTURAL ENGINEER TO ASSESS
  EXISTING STRUCTURAL ELEMENTS AND
  COMPLY WITH LOCAL BUILDING CODE.





## CEILING RESTROOM PARTITION SUPPORT

REV. NO. 001	DWG. NO.
REV. DATE: 08-27-20	AC-05
DRAWN BY: NBS	SCALE: NTS